

# Medical Device Alert

## Action

Ref: MDA/2010/088 Issued: 17 November 2010 at 15:00


### Device

Uterine sounds.

Manufactured by Rocket Medical plc.

Model number R57420, lot 416163.

Model number R60547, lots 416367 and 416818.



### Problem

Incorrect moulding of uterine sound stem has resulted in a shorter length device.

The uterine sound will not function correctly with a missing distal tip and the condition of the stem could cause injury.

### Action

- Identify affected devices using model and lot numbers.
- Do not use affected devices and arrange for their return to Rocket Medical.

### Action by

Surgeons, theatre managers, operating theatre and supplies staff

### CAS deadlines

Action underway: 01 December 2010  
Action complete: 17 December 2010

### Contact

**Manufacturer**  
Ms Jackie B Irwin  
Rocket Medical plc  
Tel: 0191 419 4488  
Email: [jackie@rocketmedical.com](mailto:jackie@rocketmedical.com)

## Link to full Medical Alert

[www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON099962](http://www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON099962)