

Medical Device Alert

Action

Ref: MDA/2009/036 Issued: 02 June 2009 at 10:30

Device

Intravenous burette administration set manufactured by Codan.

Product code 593310.

Batch numbers F74916-1 and F74916-2 only.

NHS Supply Chain code FSB003 (England only).

Problem

The manufacturer has identified the potential for leakage from the drip chamber of certain burette sets. This could result in inadequate intravenous administration.

Action

- Identify devices with batch numbers F74916-1 or F74916-2 and place them into quarantine.
- Contact Codan, who will arrange collection of the product and provide replacement or credit.

Action by

Nursing staff and supplies departments.

CAS deadlines

Action underway: 16 June 2009

Action complete: 30 June 2009

Contact

Manufacturer
Charlie Callaghan
Codan Ltd

Tel: 0118 978 3663

Fax: 0118 977 6274

E-mail: cc@codanmed.co.uk

Link to full Medical Device Alert

<http://www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON046719>