

Medical Device Alert

Action

Ref: MDA/2009/066 Issued: 26 October 2009 at 14:00

Device

Battery chargers supplied with Aquila and Neptune bath lifts manufactured by Mountway Ltd.



Problem

The surface of the battery charger can get excessively hot in use. There is potential for injury if the unit is touched, especially for those with low skin sensitivity or poor circulation.

Action

1. Trace affected chargers.
2. Contact Mountway to obtain replacement units.
3. Arrange for existing chargers to be replaced.

Action by

All those involved in the supply, maintenance and use of these bath lifts. In particular: equipment store managers, occupational therapists, care staff, maintenance staff and contractors.

Contact

Manufacturer

Customer Services
Mountway Ltd

Tel: 0800 014 1852

Fax: 01495 723 360

E-mail: customerservices@mountway.co.uk

CAS deadlines

Action underway: 26 November 2009

Action complete: 26 January 2010

[Link to full Medical Device Alert](http://www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON060096)

<http://www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON060096>